

# CTI 2572-B and 2500C-2572-B Firmware Revision History

\*\*\*\*\*

## Firmware Version 1.30 (11/5/2018)

\*\*\*\*\*

**Issues Resolved:** Product data, such as the Serial number and MACID, and IP address parameters could occasionally become corrupted, causing the module to fail the next time it was restarted. The firmware was modified to detect and correct this problem.

\*\*\*\*\*

## Firmware Version 1.27 (10/1/2018)

\*\*\*\*\*

### Issues Resolved:

**1374:** Obsolescence required replacing the old Altera FPGA with a new part. The firmware was modified to recognize the presence the new (Lattice) FPGA.

\*\*\*\*\*

## Firmware Version 1.25 (5/24/2018)

\*\*\*\*\*

### Issues Resolved:

**1258:** Module WX1 bit 7 was erroneously being set when backplane voltage exceeded the high voltage threshold. Bit 7 should have been set only when the backplane voltage drops *below* the low voltage threshold. Note: Bit 8 will now be used to indicate the high voltage condition.

**1293:** The Configuration Lock switch did not prevent a user from restarting the module via the product web page as intended.

**1337:** When the product was configured for PLC Start, the CAMP Server statistics presented by the product web server contained random information while waiting for the PLC to initiate startup. The firmware was changed to zero out all statistics until the Camp Server was started.

**1339:** The module IP address verification routine erroneously disallowed a valid IP address subnet combination (192.168.1.8 with a subnet mask of 255.255.252.0).

**1234:** The section of flash memory that contains the network configuration can become corrupted during an IP address change when power is lost at the same time the flash sector is being written. This version contains improvements that mitigate the impact of this anomaly.

### New Features and Improvements

**1322/1323:** Added support for Rev E hardware, which uses a Lattice FPGA for the backplane interface.

**1343:** Updated the board support package for the processor to the latest version.

\*\*\*\*\*

## Firmware Version 1.13 (9/20/2016)

\*\*\*\*\*

### Issues Resolved:

**1218:** The module would delay several seconds before sending a reply to an invalid NITP command.

- 1220:** Using the PLC start option, when the PLC Start Network Services changed the IP address stored in flash to an IP address that was a duplicate of another host on the network, the Multi-Segment Display continued to display the previously stored IP address.
- 1229:** The module Multi-Segment Display (MSD) would occasionally stop displaying data.
- 1230:** The user was able to enter an IP Address/ Subnet Mask combination for the module that erroneously resulted in a host address of 0 or a broadcast address.
- 1231:** Initiating a reset to factory default values, by holding down the reset button for 10 seconds or more, erroneously set the serial number and manufacturing date to default values.
- 1242:** Web page navigation would sometimes stop working.
- 1249:** Due to timing problem, erroneous bit values were occasionally written to module WX1 and WX2 words.

**New Features and Improvements:**

- 1219:** Added a logging event to indicate when the MAC address obtained from module flash memory is invalid (not a CTI MAC address).
- 1225:** Added a Power Statistics Web Page to assist in detecting base power supply problems.
- 1237:** Revised Web Page headings to accommodate both Classic (2572-B) and Compact (2500C-2572-B) products.
- 1240:** On the PLC Interface web page, revised the “Current number max allowed TC messages” statistic to indicate the source that set task codes per scan parameter (PLC or SW11 on the module).
- 1241:** Modified the text color of event log entries so that only system startup events were displayed in green text.

\*\*\*\*\*

**Firmware Version 1.03 (7/20/2016)**

\*\*\*\*\*

Original Production Release (2572-B)